


Addendum to the 9560 User's Manual

The Terminal Port of the 9560E Transaction Manager is not available for use. Terminal Port functions described in the *9560 Transaction Manager User's Manual* are not supported.



Intermec

A Western Atlas Company
6001 36th Avenue West
P.O. Box 4280
Everett, WA 98203-9280

© 1995 Intermec Corporation
All Rights Reserved
P/N 064192-001